
Reinforcement of a horizontal tank shell

LOCATION

Pardubice, Czechia

PERIOD

2024



Photograph from the project.

KEY PARAMETERS

12 × 2.7 m tank

4 plates per drawing

6 mm plate per drawing

Indicative financial band

CZK 100,000-500,000

Invoiced tank repair; excluding VAT

Installation and service work

Repair of a horizontal tank shell measuring 12 × 2.7 m in Pardubice. The solution addressed deformed areas near the concrete supports and installation of formed reinforcing plates while retaining the surrounding structures.

SCOPE OF WORK

- Tank shell repair at the concrete support locations
- Manufacturing drawing for four formed 6 mm reinforcing plates
- Vessel lifting with jacks as specified in the installation proposal
- Reinforcement installation, welding and inspection

EMKO project portfolio. Supplier at the time of delivery: EMKO HOLDING s.r.o.